



**TATAC**

# **Trail Maintenance Report**

**December 2023**

# Observations

A number of trails need maintenance in order to enhance the security and experience of trail users.

## **Issues identified on the trails assessed in this report:**

- Are not up to spec. in regard to width
- Need grading/stone dust addition
- Tree hazard
- Have grass/vegetation overgrowth

# Trails requiring maintenance

- White's Bay Trail
- Sixth St., near Black Ash Trail
- Black Ash Trail, south of Sixth St.
- Currie Farm Trail
- Hamilton Drain Trail
- Georgian Meadows Link Trail
- Tenth Line and Sixth St.
- Sixth St., from High Street to Tenth Line
- Underwood Creek Trail
- Walnut Trail
- Cranberry Inn Trail, Hwy 26, between Harbour St. and Cranberry Trail East
- Harbourview Trail at Hwy 26 (by St Louis BBQ)

# White's Bay Trail



## Issue:

- Trail width from Sheffield Ct.

## Recommendation:

- Widen Trail
- Remove grass overgrowth



# White Bay's Trail



Issue:

- Tree hazard

Recommendation:

- Remove tree as it obstructs the trail and could fall on cyclists/walkers



# Whyte's Bay Trail



Issue:


- Geo tex material poking through the trail

Recommendation:

- Stone dust needs to be added



# Sixth St., near Black Ash Trail



Issue:

- Trail width
- Hazard

Recommendation:

- Widen trail
- Fix hazard  
(mailbox/metal rod)



# Black Ash Trail, South of Sixth St.



Issue:

- Width (not even 5')

Recommendation:

- Widen trail
- Remove grass overgrowth



# Currie Farm Trail/Georgian M Link



Issue:

- Trail washes out (at base of asphalt)

Recommendation:

- Install better drainage
- Add stone dust to level grade



# Hamilton Drain Trail



## Issue:

- New sand stone screenings are too deep - not properly compacted
- Ground water situation still an issue – many houses on the south side of Hughes have eaves troughs and sump pumps draining on to the trail or just in front of it.

## Recommendation:

- Redo compacting of sand stone screenings
- Address drainage issue to avoid flooding on the trail



# Georgian Meadows Link Trail



## Issue:

- Recently redone but not up to spec

## Recommendation:

- Should be redone properly, up to spec



# Georgian Meadows Link Trail



Issue:

- Width
- Drain not level

Recommendation:

- Widen trail
- Level drain
- Add stone dust



# Tenth Line and Sixth St.



## Issue:

- Width
- Vegetation overgrowth

## Recommendation:

- Widen trail
- Remove vegetation overgrowth
- Add stone dust



# Sixth St from High St to Tenth Line



Issue:

- Width
- Vegetation overgrowth

Recommendation:

- Widen trail
- Remove vegetation overgrowth
- Add stone dust



# Underwood Creek Trail



Issue:

- Width
- Needs stone dust

Recommendation:

- Widen trail
- Remove grass overgrowth
- Add stone dust



# Walnut Trail



Issue:

- Barricades (do we really need them?)

Recommendation:

- Remove barricades



# Cranberry Inn Trail, Hwy 26

Cranberry Inn Trail  
Between Harbour St. and Cranberry Trail  
East

Issue:

- Width
- Grass overgrowth
- Grading

Recommendation:

- Widen trail
- Remove grass overgrowth
- Add stone dust to level grade

# Harbourview Trail and Hwy 26



Issue:

- Trail ends, no direction

Recommendation:

- Reconfigure trail continuation